## BUILDING SAFETY CERTIFICATE

NO 4028

Date-1308 2024

It is certified that the existing building PODAR INTERNATIONAL SCHOOL at Survey No-165'2 Mouza Datala New Chandrapur Township. Chandrapur-442406 (M.S.) is having blocks. Thors as per details below.

Details of Block (1) Block (2) Block (3) Block (4) Block (5)

Blocks in

School

No of Floors Zero Basement +
Ground Floor +
First Floor

The building is owned / occupied by PODAR INTERNATIONAL SCHOOL have complied with the Building Safety requirement in accordance with National Building Code Rules and verified by the officers concerned of Public Works Division-1, Chandrapur on 14.08.2024 in the presence of Mr Amey Kanhere (Admin Officer) at Survey No-165/2 Mouza Datala, New Chandrapur Township. Chandrapur-442406 (M.S) and that building / premises is fit for occupancy for running school with effect from 14.08.2024 for a period of One Year in accordance with rule and subject to compliance of the specific condition as appended

Issue on Dt 14.03.2024 at Chandrapur by

"Stoke out whichever is not applicable in case of block is more than six separate sheets for detail.

Signature with Seal

Name-

यु. वि. कुंभे

Designation Executive Engilater क. १

Name & Address of Department office Public Work Division 1

Chandrapur

Dr. Valmik Somase
Principal CBSE (Not See Principal CBSE (Not See Podar International School Datala, New Chandrapur, PIN-442406 CBSE Affiliation No. 1130772

Manager
Podar Inernational School
Mouza datala-Chandrapur